



Apsley Package: Coles Bay Road Junction to Bicheno crash statistics

| ID | VCRN | DOA DESCRIPTION | CRASH DATE | REPORT DATE | SEVERITY | VISITED | SURFACE TYPE | SURFACE CONDITIONS | LIGHT CONDITION | CENTRE LINE | SPEED ZONE | LOCATION DESCRIPTION | DIER ROAD NO | DIER ROAD LINK NO | DIER CWY CODE | DIER CHRG | CRASH TIME MS | UNIT TYPES | LAT | LOX | |
|----------|----------|-----------------------------------------------------------|---------------------|-------------|----------------------|---------|--------------|------------------------------------------|---------------------------------|-------------------------------------|------------|---------------------------------------------------------------------------------|--------------|-------------------|---------------|-----------|---------------|------------|------------------------------|------------|--------------|
| 3003557 | | 181 - Off left bend into object/parked vehicle | 2011-05-01T04:00:00 | 2011-04-30 | Minor | Yes | Sealed | Wet | Daylight | Double - one broken, one continuous | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 3.42 | 1.30E+12 | Light Vehicle | 148.245108 | -41.91759804 |
| 30062817 | | 130 - Vehicles in same lane/ rear end | 2011-11-25T12:00:00 | 2010-11-25 | Property Damage Only | No | Sealed | Dry | Daylight | Double continuous | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 6.07 | 1.25E+12 | Light Vehicle | 148.255808 | -41.896129 |
| 30015486 | | 187 - Animal (not ridden) | 2006-11-23T11:00:00 | 2006-11-23 | Property Damage Only | No | Sealed | Dry | Darkness (without street light) | None | 80 | Harveys Farm Road, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | | 1.06E+12 | Light Vehicle | 148.300375 | -41.887499 |
| 30015117 | | 181 - Off left bend into object/parked vehicle | 2007-03-07T22:00:00 | 2007-03-07 | Minor | Yes | Sealed | Dry - Poor road shoulder/verge condition | Daylight | Double continuous | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 8.53 | 1.17E+12 | Motorcycle | 148.282583 | -41.8875564 |
| 20010275 | | 180 - Off carriageway left bend | 2001-02-04T03:00:00 | 2001-02-14 | Property Damage Only | No | Sealed | Dry | Daylight | Double continuous | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 9.65 | 9.81E+11 | Light Vehicle | 148.255075 | -41.88711932 |
| 20010998 | | 180 - Off carriageway right bend | 2001-03-04T03:00:00 | 2001-01-21 | Property Damage Only | No | Sealed | Dry | Daylight | Double continuous | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 0.81 | 9.84E+11 | Light Vehicle | 148.224789 | -41.9343882 |
| 20022010 | | 171 - Left off carriageway into object or parked vehicle | 2001-03-29T02:00:00 | 2002-06-21 | Minor | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 2.92 | 1.02E+12 | Light Vehicle | 148.241803 | -41.9214933 |
| 20010178 | | 180 - Off carriageway right bend | 2001-02-11T04:00:00 | 2001-01-04 | Minor | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 5.96 | 9.82E+11 | Light Vehicle | 148.255135 | -41.88691914 |
| 20012672 | | 181 - Off right bend into object/parked vehicle | 2001-05-25T14:10:00 | 2001-05-18 | Minor | Yes | Sealed | Dry | Darkness (without street light) | Single broken | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 4.99 | 9.91E+11 | Light Vehicle | 148.253459 | -41.9055489 |
| 20033364 | | 181 - Off carriageway left bend | 2001-10-21T13:00:00 | 2001-12-02 | Property Damage Only | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 10.44 | 1.00E+12 | Light Vehicle | 148.209430 | -41.8846077 |
| 20041379 | | 171 - Right off carriageway into object or parked vehicle | 2004-02-24T02:30:00 | 2004-04-26 | Property Damage Only | Yes | Sealed | Dry | Daylight | Single broken | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 5.29 | 1.08E+12 | Light Vehicle | 148.254031 | -41.90281815 |
| 20041387 | | 171 - Right off carriageway into object or parked vehicle | 2004-03-17T00:00:00 | 2004-08-25 | Property Damage Only | No | Sealed | Dry | Daylight | Single broken | 100 | Coles Bay Road, Bicheno, Glamorgan-Spring Bay | A2632 | | 5 | A | 0.2 | 1.08E+12 | Light Vehicle | 148.222192 | -41.94028562 |
| 20034077 | | 175 - Off end of road T junctions/intersection | 2003-08-03T09:30:00 | 2003-09-18 | Property Damage Only | No | Sealed | Dry | Darkness (without street light) | Not stated | 100 | Intersection of Coles Bay Road and Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 40 | A | 11.77 | 1.06E+12 | Light Vehicle | 148.219963 | -41.94060008 |
| 20034077 | | 175 - Off end of road T junctions/intersection | 2003-08-03T09:30:00 | 2003-09-18 | Property Damage Only | No | Sealed | Dry | Darkness (without street light) | Not stated | 100 | Intersection of Coles Bay Road and Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 11.77 | 1.06E+12 | Light Vehicle | 148.219963 | -41.94060008 |
| 20034077 | | 175 - Off end of road T junctions/intersection | 2003-08-03T09:30:00 | 2003-09-18 | Property Damage Only | No | Sealed | Dry | Darkness (without street light) | Not stated | 100 | Intersection of Coles Bay Road and Tamam Highway, Bicheno, Glamorgan-Spring Bay | A2632 | | 5 | A | 11.77 | 1.06E+12 | Light Vehicle | 148.219963 | -41.94060008 |
| 20041302 | | 151 - Out of control | 2004-02-20T04:00:00 | 2004-04-02 | Minor | Yes | Sealed | Dry | Daylight | Single broken | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 4.27 | 1.08E+12 | Light Vehicle | 148.251412 | -41.91081935 |
| 20040721 | | 120 - Wrong side/other head on (not overtaking) | 2004-01-27T22:50:00 | 2004-08-08 | Property Damage Only | No | Sealed | Wet | Daylight | None | 0 | Off road at Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 13.97 | 1.08E+12 | Heavy Vehicle; Light Vehicle | 148.280481 | -41.8897453 |
| 20030950 | | 118 - Two left turn | 2003-02-21T02:15:00 | 2003-04-14 | Property Damage Only | Yes | Sealed | Wet | Daylight | Not stated | 100 | Intersection of Coles Bay Road and Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 40 | A | 11.77 | 1.05E+12 | Light Vehicle | 148.219963 | -41.94060008 |
| 20030950 | | 118 - Two left turn | 2003-02-21T02:15:00 | 2003-04-14 | Property Damage Only | Yes | Sealed | Wet | Daylight | Not stated | 100 | Intersection of Coles Bay Road and Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 11.77 | 1.05E+12 | Light Vehicle | 148.219963 | -41.94060008 |
| 20030950 | | 118 - Two left turn | 2003-02-21T02:15:00 | 2003-04-14 | Property Damage Only | Yes | Sealed | Wet | Daylight | Not stated | 100 | Intersection of Coles Bay Road and Tamam Highway, Bicheno, Glamorgan-Spring Bay | A2632 | | 5 | A | 11.77 | 1.05E+12 | Light Vehicle | 148.219963 | -41.94060008 |
| 20043749 | | 187 - Animal (not ridden) | 2004-07-03T10:27:00 | 2004-09-22 | Property Damage Only | Yes | Sealed | Dry | Darkness (without street light) | Single broken | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 0 | 1.09E+12 | Light Vehicle | 148.214086 | -41.9382431 |
| 30017173 | | 181 - Off left bend into object/parked vehicle | 2006-01-18T22:30:00 | 2006-01-17 | Fatal | Yes | Sealed | Dry | Daylight | Single broken | 100 | Coles Bay Road, Bicheno, Glamorgan-Spring Bay | A2632 | | 5 | A | 0.22 | 1.14E+12 | Light Vehicle | 148.224877 | -41.94026007 |
| 30015052 | | 132 - Vehicles in same lane/ right rear | 2009-12-04T02:50:00 | 2009-12-03 | Property Damage Only | Yes | Sealed | Dry | Daylight | None | 80 | Harveys Farm Road, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | | 1.18E+12 | Light Vehicle | 148.300787 | -41.89334459 |
| 30015128 | | 130 - Vehicles in same lane/ rear end | 2009-01-10T05:10:00 | 2008-06-09 | Property Damage Only | Yes | Sealed | Dry | Daylight | Double - one broken, one continuous | 100 | Coles Bay Road, Bicheno, Glamorgan-Spring Bay | A2632 | | 5 | A | 0.33 | 1.14E+12 | Light Vehicle | 148.218002 | -41.9401269 |
| 30062663 | | 181 - Off carriageway left bend | 2009-01-09T21:00:00 | 2009-01-10 | Minor | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 2.09 | 1.28E+12 | Light Vehicle | 148.212857 | -41.94211494 |
| 30054428 | | 121 - Right through | 2009-04-08T23:51:00 | 2009-04-09 | Serious | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Intersection of Coles Bay Road and Tamam Highway, Bicheno, Glamorgan-Spring Bay | A2632 | | 5 | A | 0 | 1.24E+12 | Light Vehicle | 148.219938 | -41.94065529 |
| 30054428 | | 121 - Right through | 2009-04-08T23:51:00 | 2009-04-09 | Serious | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Intersection of Coles Bay Road and Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 40 | A | 11.77 | 1.24E+12 | Light Vehicle | 148.219938 | -41.94065529 |
| 30054428 | | 121 - Right through | 2009-04-08T23:51:00 | 2009-04-09 | Serious | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Intersection of Coles Bay Road and Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | | 1.24E+12 | Light Vehicle | 148.219938 | -41.94065529 |
| 30054430 | | 184 - Out of control on carriageway | 2009-04-18T04:18:00 | 2009-04-17 | First Aid | Yes | Sealed | Dry | Daylight | Double - one broken, one continuous | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 8.53 | 1.24E+12 | Motorcycle | 148.282631 | -41.88785687 |
| 30051535 | | 171 - Left off carriageway into object or parked vehicle | 2009-02-17T04:20:00 | 2009-02-17 | Property Damage Only | Yes | Sealed | Dry | Daylight | Single broken | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 3.11 | 1.23E+12 | Light Vehicle | 148.243099 | -41.9197248 |
| 30062661 | | 170 - Off carriageway to left | 2009-01-25T11:55:00 | 2009-01-25 | Property Damage Only | Yes | Sealed | Dry | Darkness (without street light) | Double - one broken, one continuous | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 0.49 | 1.23E+12 | Light Vehicle | 148.212857 | -41.94211494 |
| 30054449 | | 189 - Other danger | 2010-10-21T06:30:00 | 2010-10-21 | First Aid | No | Sealed | Dry | Daylight | Not known | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 1.64 | 1.29E+12 | Light Vehicle | 148.229713 | -41.9279535 |
| 30054461 | | 187 - Animal (not ridden) | 2009-05-21T07:40:00 | 2010-05-22 | Property Damage Only | No | Sealed | Dry | Darkness (without street light) | Double continuous | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 40 | A | 11.47 | 1.27E+12 | Motorcycle | 148.217478 | -41.9428782 |
| 30054466 | | 181 - Off carriageway right bend | 2009-01-11T04:46:00 | 2010-01-10 | Minor | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 11.64 | 1.28E+12 | Light Vehicle | 148.219938 | -41.94065529 |
| 30015108 | | 184 - Out of control on carriageway | 2006-03-21T03:30:00 | 2006-03-20 | Minor | Yes | Sealed | Dry | Daylight | Double - one broken, one continuous | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 9.73 | 1.14E+12 | Light Vehicle | 148.266417 | -41.88724474 |
| 30084252 | | 189 - Other curve | 2008-08-03T06:30:00 | 2008-08-17 | Property Damage Only | No | Sealed | Dry | Daylight | Single continuous | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 1.71 | 1.22E+12 | Motorcycle | 148.203667 | -41.92745046 |
| 154418 | 15001724 | 189 - Other curve | 2011-03-28T06:20:00 | 2011-03-27 | Property Damage Only | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 8.65 | 1.43E+12 | Light Vehicle | 148.286317 | -41.88714865 |
| 30054434 | | 181 - Off left bend into object/parked vehicle | 2009-11-20T06:12:00 | 2009-11-21 | Serious | Yes | Sealed | Dry | Daylight | Double - one broken, one continuous | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 7.69 | 1.26E+12 | Light Vehicle | 148.272584 | -41.8889136 |
| 30090490 | | 130 - Vehicles in same lane/ rear end | 2009-12-12T03:30:00 | 2009-12-12 | Property Damage Only | No | Sealed | Dry | Daylight | Single Continuous | 100 | Intersection of Coles Bay Road and Tamam Highway, Bicheno, Glamorgan-Spring Bay | A2632 | | 5 | A | 0 | 1.26E+12 | Light Vehicle | 148.219963 | -41.94060008 |
| 30090490 | | 130 - Vehicles in same lane/ rear end | 2009-12-12T03:30:00 | 2009-12-12 | Property Damage Only | No | Sealed | Dry | Daylight | Single Continuous | 100 | Intersection of Coles Bay Road and Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 40 | A | 11.77 | 1.26E+12 | Light Vehicle | 148.219963 | -41.94060008 |
| 30090490 | | 130 - Vehicles in same lane/ rear end | 2009-12-12T03:30:00 | 2009-12-12 | Property Damage Only | No | Sealed | Dry | Daylight | Single Continuous | 100 | Intersection of Coles Bay Road and Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 0 | 1.26E+12 | Light Vehicle | 148.219963 | -41.94060008 |
| 30017474 | | 174 - Out of control on carriageway | 2009-09-13T08:00:00 | 2009-09-13 | Serious | Yes | Unsealed | Dry | Dawn / Dusk | None | 100 | Courland Bay Road, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | | 1.25E+12 | Motorcycle | 148.295107 | -41.90034422 |
| 30054433 | | 173 - Right off carriageway into object or parked vehicle | 2009-11-08T09:50:00 | 2009-11-07 | Serious | Yes | Sealed | Dry | Darkness (without street light) | Double continuous | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 3.88 | 1.48E+12 | Light Vehicle | 148.248716 | -41.91472425 |
| 3002658 | 1700884 | 184 - Out of control on carriageway | 2017-03-27T23:26:00 | 2017-04-04 | Serious | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 8.61 | | Motorcycle | 148.282377 | -41.88748418 |
| 30062652 | | 171 - Off carriageway to right | 2009-01-03T03:56:00 | 2007-12-31 | First Aid | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 11.53 | 1.20E+12 | Light Vehicle | 148.218813 | -41.94242529 |
| 30062812 | | 171 - Left off carriageway into object or parked vehicle | 2010-03-24T03:30:00 | 2010-03-24 | Property Damage Only | Yes | Sealed | Dry | Daylight | Single broken | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 0.98 | 1.27E+12 | Light Vehicle | 148.249764 | -41.9131609 |
| 30079508 | | 151 - Out of control | 2010-03-24T03:30:00 | 2010-03-24 | Minor | Yes | Sealed | Dry | Daylight | Single broken | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 4.08 | 1.27E+12 | Light Vehicle | 148.249768 | -41.9131614 |
| 30054455 | | 181 - Off right bend into object/parked vehicle | 2010-02-15T03:34:00 | 2010-02-14 | Minor | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 11.65 | 1.27E+12 | Light Vehicle | 148.219938 | -41.94065529 |
| 30054458 | | 184 - Out of control on carriageway | 2010-03-20T18:54:00 | 2010-03-20 | Minor | Yes | Sealed | Dry | Darkness (without street light) | Double continuous | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 6.01 | 1.27E+12 | Light Vehicle | 148.254008 | -41.8956611 |
| 372040 | 14004248 | 181 - Off right bend into object/parked vehicle | 2014-08-20T00:35:00 | 2014-08-19 | Minor | Yes | Sealed | Dry | Daylight | Single Continuous | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 6.42 | 1.41E+12 | Light Vehicle | 148.259775 | -41.89521197 |
| 180 | | 180 - Off carriageway right bend | 2012-11-12T08:50:00 | 2012-11-12 | Property Damage Only | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 9.51 | 1.35E+12 | Light Vehicle | 148.219815 | -41.88681471 |
| 30062022 | | 173 - Right off carriageway into object or parked vehicle | 2012-01-11T03:30:00 | 2012-01-11 | Minor | Yes | Sealed | Dry | Daylight | Double continuous | 60 | Tamam Highway, Bicheno, Glamorgan-Spring Bay | A0113 | | 42 | A | 5.04 | 1.36E+12 | Light Vehicle | 148.235616 | -41.9050505 |
| 2009904 | 1700168 | 181 - Off right bend into object/parked vehicle | 2017-10-07T23:00:00 | 2017-10-02 | Property Damage Only | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamam Highway, B | | | | | | | | | |

| | | | | | | | | | | | | | | | | | | | |
|----------|----------|------------------------------------------------------------------|----------------------|-------------|----------------------|-----|----------|-----------------------------------------|---------------------------------|-------------------------------------|-----------|----------------------------------------------------------------------------------|-------|----|---|-------|---------------------------|-------------|--------------|
| 51506135 | 22000108 | 181 - Off right bend into object/parked vehicle | 2022-01-06T01:55:00Z | 2022-01-06Z | Property Damage Only | Yes | Sealed | Wet | Daylight | Double continuous | 100 | Tasman Highway, Bicheno, Glamorgan-Spring Bay | A0113 | 40 | A | 11.65 | Light Vehicle | 148.2191949 | -41.94159401 |
| 51462071 | 21007230 | 181 - Off right bend into object/parked vehicle | 2021-11-23T06:05:00Z | 2021-11-22Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tasman Highway, Bicheno, Glamorgan-Spring Bay | A0113 | 42 | A | 1.99 | Light Vehicle | 148.2191526 | -41.9248549 |
| 51218139 | 21003884 | 172 - Off carriageway to right | 2021-06-18T02:51:00Z | 2021-06-17Z | Minor | Yes | Sealed | Wet | Daylight | Double continuous | 100 | Tasman Highway, Bicheno, Glamorgan-Spring Bay | A0113 | 40 | A | 11.37 | Light Vehicle | 148.2163179 | -41.94260132 |
| 51297993 | 21004139 | 139 - Other same direction (including vehicle rolling backwards) | 2021-06-29T01:51:00Z | 2021-06-28Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Single broken | 40 | Tasman Highway, Bicheno, Glamorgan-Spring Bay | A0113 | 42 | A | 6 | Heavy Vehicle | 148.2553413 | -41.89661801 |
| 51375135 | 21005518 | 120 - Wrong side/other head on (not overtaking) | 2021-08-29T10:00:00Z | 2021-08-29Z | Property Damage Only | Yes | Sealed | Dry | Darkness (without street light) | Double continuous | 80 | Tasman Highway, Bicheno, Glamorgan-Spring Bay | A0113 | 42 | A | 6 | Light Vehicle | 148.2533032 | -41.89666661 |
| 50303817 | 19006166 | 139 - Other overtaking | 2019-10-23T06:01:00Z | 2019-10-23Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Single broken | 100 | Tasman Highway, Bicheno, Glamorgan-Spring Bay | A0113 | 42 | A | 6.66 | Light Vehicle | 148.2637005 | -41.8986234 |
| 49197720 | 18002052 | 189 - Other curve | 2018-04-01T10:10:00Z | 2018-04-11Z | First Aid | Yes | Sealed | Dry, Poor road shoulder/verge condition | Darkness (without street light) | Double - one broken, one continuous | 100 | Bicheno, Glamorgan-Spring Bay and Tasman Highway, Bicheno, Glamorgan-Spring Bay | A2632 | 5 | A | 0 | Light Vehicle | 148.2198898 | -41.94065121 |
| 49197720 | 18002052 | 189 - Other curve | 2018-04-01T10:10:00Z | 2018-04-11Z | First Aid | Yes | Sealed | Dry, Poor road shoulder/verge condition | Darkness (without street light) | Double - one broken, one continuous | 100 | Bicheno, Glamorgan-Spring Bay | A0113 | 40 | A | 11.77 | Light Vehicle | 148.2198898 | -41.94065121 |
| 49197720 | 18002052 | 189 - Other curve | 2018-04-01T10:10:00Z | 2018-04-11Z | First Aid | Yes | Sealed | Dry, Poor road shoulder/verge condition | Darkness (without street light) | Double - one broken, one continuous | 100 | Bicheno, Glamorgan-Spring Bay and Tasman Highway, Bicheno, Glamorgan-Spring Bay | A0113 | 42 | A | 0 | Light Vehicle | 148.2198898 | -41.94065121 |
| 49384250 | 18003136 | 170 - Other straight | 2018-06-05T15:00:00Z | 2018-06-05Z | Property Damage Only | No | Sealed | Gravel or other loose material | Daylight | Single broken | Not known | Coles Bay Road, Bicheno, Glamorgan-Spring Bay | A2632 | 5 | A | 0.47 | Light Vehicle | 148.225481 | -41.90208868 |
| 49838094 | 19000628 | 110 - Cross traffic | 2019-02-01T07:14:00Z | 2019-01-31Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Double - one broken, one continuous | 100 | Bicheno, Glamorgan-Spring Bay | A2632 | 5 | A | 0 | Light Vehicle | 148.2198898 | -41.94065121 |
| 49838094 | 19000628 | 110 - Cross traffic | 2019-02-01T07:14:00Z | 2019-01-31Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Double - one broken, one continuous | 100 | Intersection of Coles Bay Road and Tasman Highway, Bicheno, Glamorgan-Spring Bay | A0113 | 40 | A | 11.77 | Light Vehicle | 148.2198898 | -41.94065121 |
| 49838094 | 19000628 | 110 - Cross traffic | 2019-02-01T07:14:00Z | 2019-01-31Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Double - one broken, one continuous | 100 | Intersection of Coles Bay Road and Tasman Highway, Bicheno, Glamorgan-Spring Bay | A0113 | 42 | A | 0 | Light Vehicle | 148.2198898 | -41.94065121 |
| 49816507 | 19003232 | 121 - Right through | 2019-01-17T02:30:00Z | 2019-01-17Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Single Continuous | 100 | Bicheno, Glamorgan-Spring Bay | A2632 | 5 | A | 0 | Light Vehicle | 148.2198898 | -41.94065121 |
| 49816507 | 19003232 | 121 - Right through | 2019-01-17T02:30:00Z | 2019-01-17Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Single Continuous | 100 | Intersection of Coles Bay Road and Tasman Highway, Bicheno, Glamorgan-Spring Bay | A0113 | 40 | A | 11.77 | Light Vehicle | 148.2198898 | -41.94065121 |
| 49816507 | 19003232 | 121 - Right through | 2019-01-17T02:30:00Z | 2019-01-17Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Single Continuous | 100 | Bicheno, Glamorgan-Spring Bay | A0113 | 42 | A | 0 | Light Vehicle | 148.2198898 | -41.94065121 |
| 50638962 | 20002247 | 181 - Off right bend into object/parked vehicle | 2020-05-02T06:00:00Z | 2020-05-02Z | Minor | Yes | Sealed | Wet | Daylight | Single Continuous | 100 | Tasman Highway, Bicheno, Glamorgan-Spring Bay | A0113 | 40 | A | 11.64 | Light Vehicle | 148.2191528 | -41.94163528 |
| 50925098 | 21000571 | 184 - Out of control on carriageway | 2020-12-31T08:40:00Z | 2021-01-04Z | Minor | Yes | Sealed | Wet | Daylight | Double continuous | 100 | Tasman Highway, Bicheno, Glamorgan-Spring Bay | A0113 | 42 | A | 6 | Light Vehicle | 148.2533897 | -41.89663601 |
| 50891421 | 20006050 | 189 - Other curve | 2020-12-04T02:30:00Z | 2020-12-03Z | Minor | Yes | Sealed | Dry | Daylight | Single Continuous | 100 | Tasman Highway, Bicheno, Glamorgan-Spring Bay | A0113 | 42 | A | 8.38 | Motorcycle | 148.2807965 | -41.88779334 |
| 50930856 | 21000008 | 181 - Off right bend into object/parked vehicle | 2021-01-01T02:20:00Z | 2020-12-31Z | Minor | Yes | Sealed | Dry, Poor road shoulder/verge condition | Daylight | Single Continuous | 100 | Tasman Highway, Bicheno, Glamorgan-Spring Bay | A0113 | 40 | A | 11.65 | Light Vehicle | 148.2192101 | -41.9415834 |
| 50290706 | 20001061 | 173 - Right off carriageway into object or parked vehicle | 2020-02-20T06:30:00Z | 2020-02-20Z | First Aid | Yes | Sealed | Dry | Daylight | Double - one broken, one continuous | 100 | Tasman Highway, Bicheno, Glamorgan-Spring Bay | A0113 | 42 | A | 3.84 | Light Vehicle | 148.2444932 | -41.91822886 |
| 50712135 | 20003674 | 181 - Off right bend into object/parked vehicle | 2020-07-28T11:10:00Z | 2020-07-29Z | Property Damage Only | Yes | Sealed | Wet | Daylight | Double continuous | 100 | Tasman Highway, Bicheno, Glamorgan-Spring Bay | A0113 | 42 | A | 11.51 | Light Vehicle | 148.217843 | -41.94231411 |
| 50453139 | 20003137 | 139 - Other same direction (including vehicle rolling backwards) | 2020-01-09T01:50:00Z | 2020-01-08Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Single broken | 90 | Tasman Highway, Bicheno, Glamorgan-Spring Bay | A0113 | 42 | A | 4.11 | Light Vehicle | 148.2499742 | -41.91280265 |
| 50402838 | 19007281 | 167 - Animal (not ridden) | 2019-12-14T07:00:00Z | 2019-12-14Z | Property Damage Only | No | Sealed | Dry | Daylight | Single broken | 100 | Coles Bay Road, Bicheno, Glamorgan-Spring Bay | A2632 | 5 | A | 1.94 | Light Vehicle | 148.2510304 | -41.94338407 |
| 50672743 | 20002764 | 120 - Wrong side/other head on (not overtaking) | 2020-06-07T22:50:00Z | 2020-06-07Z | Minor | Yes | Sealed | Dry | Daylight | Double - one broken, one continuous | 100 | Tasman Highway, Bicheno, Glamorgan-Spring Bay | A0113 | 42 | A | 5.61 | Light Vehicle | 148.2549318 | -41.90007426 |
| 50618386 | 20002052 | 181 - Off right bend into object/parked vehicle | 2020-04-13T09:30:00Z | 2020-04-13Z | Property Damage Only | Yes | Sealed | Dry | Darkness (without street light) | None | 60 | Harveys Farm Road, Bicheno, Glamorgan-Spring Bay | | | | | Light Vehicle | 148.3004638 | -41.8887342 |
| 50592519 | 20001128 | 189 - Other curve | 2020-02-24T01:50:00Z | 2020-02-23Z | Minor | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tasman Highway, Bicheno, Glamorgan-Spring Bay | A0113 | 42 | A | 8.52 | Motorcycle | 148.2824845 | -41.88785729 |
| 50207100 | 19004801 | 181 - Off right bend into object/parked vehicle | 2019-08-03T22:15:00Z | 2019-08-18Z | Minor | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tasman Highway, Bicheno, Glamorgan-Spring Bay | A0113 | 42 | A | 5.67 | Light Vehicle | 148.2520335 | -41.89956168 |
| 51700587 | 22003344 | 189 - Other curve | 2022-06-13T04:10:00Z | 2022-06-12Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tasman Highway, Bicheno, Glamorgan-Spring Bay | A0113 | 42 | A | 2.56 | Light Vehicle | 148.2354213 | -41.92625964 |
| 51864508 | 23000118 | | 2023-01-07T05:05:00Z | 2023-01-06Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tasman Highway, Apslwam, Glamorgan-Spring Bay | | | | | Light Vehicle | 148.2126093 | -41.94209044 |
| 51831487 | 22007104 | | 2022-12-07T05:05:00Z | 2022-12-07Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tasman Highway, Bicheno, Glamorgan-Spring Bay | | | | | Light Vehicle | 148.262637 | -41.9364252 |
| 51695170 | 22003243 | 173 - Right off carriageway into object or parked vehicle | 2022-06-07T08:40:00Z | 2022-06-07Z | First Aid | Yes | Sealed | Dry | Darkness (without street light) | Single broken | 80 | Tasman Highway, Bicheno, Glamorgan-Spring Bay | A0113 | 42 | A | 7.03 | Light Vehicle | 148.2658397 | -41.89198378 |
| 51833600 | 22007141 | 149 - Other manoeuvring | 2022-12-04T01:30:00Z | 2022-12-08Z | Minor | No | Unsealed | Not known | Daylight | None | Not known | Off road at Bicheno, Glamorgan-Spring Bay | | | | | Motorcycle | 148.2907006 | -41.8871118 |
| 51788441 | 22005070 | 173 - Right off carriageway into object or parked vehicle | 2022-09-04T12:00:00Z | 2022-09-04Z | Property Damage Only | Yes | Sealed | Dry | Darkness (without street light) | Single Continuous | 100 | Tasman Highway, Bicheno, Glamorgan-Spring Bay | A0113 | 42 | A | 7.03 | Light Vehicle | 148.2658381 | -41.89198383 |
| 51823046 | 22006968 | 189 - Other curve | 2022-11-01T06:20:00Z | 2022-11-01Z | Minor | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tasman Highway, Bicheno, Glamorgan-Spring Bay | A0113 | 42 | A | 8.54 | Motorcycle | 148.2826735 | -41.88782127 |
| 51838103 | 22007249 | | 2022-12-14T00:00:00Z | 2022-12-13Z | Property Damage Only | Yes | Sealed | Wet | Daylight | Double continuous | 100 | Tasman Highway, Apslwam, Glamorgan-Spring Bay | | | | | Light Vehicle | 148.2187995 | -41.94187474 |
| 51864545 | 23000139 | 120 - Wrong side/other head on (not overtaking) | 2023-01-08T05:10:00Z | 2023-01-07Z | Serious | Yes | Sealed | Dry | Daylight | Double continuous | 80 | Tasman Highway, Bicheno, Glamorgan-Spring Bay | A0113 | 42 | A | 9.72 | Light Vehicle, Motorcycle | 148.2963529 | -41.88723966 |
| 51895174 | 23000876 | 121 - Right through | 2023-02-11T08:25:00Z | 2023-02-10Z | Minor | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Intersection of Coles Bay Road and Tasman Highway, Bicheno, Glamorgan-Spring Bay | A2632 | 5 | A | 0 | Light Vehicle | 148.2198898 | -41.94065121 |
| 51895174 | 23000876 | 121 - Right through | 2023-02-11T08:25:00Z | 2023-02-10Z | Minor | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Bicheno, Glamorgan-Spring Bay | A0113 | 40 | A | 11.77 | Light Vehicle | 148.2198898 | -41.94065121 |
| 51895174 | 23000876 | 121 - Right through | 2023-02-11T08:25:00Z | 2023-02-10Z | Minor | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Bicheno, Glamorgan-Spring Bay | A0113 | 42 | A | 0 | Light Vehicle | 148.2198898 | -41.94065121 |

| Apsley Package: Glen Gala Corner crash statistics | | | | | | | | | | | | | | | | | | | | |
|---------------------------------------------------|----------|-------------------------------|----------------------|-------------|----------------------|---------|--------------|--------------------|-----------------|-------------------|------------|-------------------------------------------------|--------------|-------------------|---------------|-----------|---------------|---------------|-------------|--------------|
| ID | VCRN | DOA DESCRIPTION | CRASH DATE TIME | REPORT DATE | SEVERITY | VISITED | SURFACE TYPE | SURFACE CONDITIONS | LIGHT CONDITION | CENTRE LINE | SPEED ZONE | LOCATION DESCRIPTION | DIER ROAD NO | DIER ROAD LINK NO | DIER CWY CODE | DIER CHNG | CRASH TIME MS | UNIT TYPES | LAT | LONG |
| 30062825 | 180 - | Off carriageway right bend | 2011-02-20T00:30:00Z | 2011-02-20Z | Minor | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tasman Highway, Cranbrook, Glamorgan-Spring Bay | A0113 | 38 | A | 8.86 | 1.30E+12 | Motorcycle | 148.0970209 | -41.99366913 |
| 20020562 | 182 - | Off carriageway left bend | 2002-02-02T01:00:00Z | 2002-03-25Z | First Aid | No | Sealed | Dry | Daylight | Not stated | | Tasman Highway, Cranbrook, Glamorgan-Spring Bay | A0113 | 38 | A | 9 | 1.01E+12 | Motorcycle | 148.0985304 | -41.99342411 |
| 30035504 | 189 - | Other curve | 2011-12-24T03:00:00Z | 2011-12-25Z | Minor | No | Sealed | Dry | Daylight | Double continuous | 100 | Tasman Highway, Cranbrook, Glamorgan-Spring Bay | A0113 | 38 | A | 9.17 | 1.32E+12 | Motorcycle | 148.0997841 | -41.89463437 |
| 30034995 | 184 - | Out of control on carriageway | 2007-10-18T06:30:00Z | 2007-10-18Z | Property Damage Only | No | Sealed | Dry | Daylight | Double continuous | 100 | Tasman Highway, Cranbrook, Glamorgan-Spring Bay | A0113 | 38 | A | 8.86 | 1.33E+12 | Motorcycle | 148.0980808 | -41.9933926 |
| 30039102 | 182 - | Off carriageway left bend | 2008-02-09T01:25:00Z | 2008-02-13Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Not stated | | Tasman Highway, Cranbrook, Glamorgan-Spring Bay | A0113 | 38 | A | 8.99 | 1.20E+12 | Motorcycle | 148.0984277 | -41.99333445 |
| 4861553 | 18005891 | 189 - Other curve | 2018-10-26T07:00:00Z | 2018-10-26Z | Serious | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tasman Highway, Cranbrook, Glamorgan-Spring Bay | A0113 | 38 | A | 8.99 | | Motorcycle | 148.0984265 | -41.9933625 |
| 51172616 | 22005861 | 189 - Other curve | 2022-02-18T05:15:00Z | 2022-02-17Z | Minor | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tasman Highway, Cranbrook, Glamorgan-Spring Bay | A0113 | 38 | A | 8.9 | | Motorcycle | 148.0974077 | -41.99336157 |
| 51213926 | 21003759 | 189 - Other curve | 2021-06-12T23:08:00Z | 2021-06-12Z | Minor | Yes | Sealed | Wet | Daylight | Double continuous | 100 | Tasman Highway, Cranbrook, Glamorgan-Spring Bay | A0113 | 38 | A | 9.17 | | Motorcycle | 148.0996088 | -41.99463665 |
| 50703758 | 20003211 | 189 - Other curve | 2020-07-04T04:00:00Z | 2020-07-03Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tasman Highway, Cranbrook, Glamorgan-Spring Bay | A0113 | 38 | A | 8.95 | | Light Vehicle | 148.0980466 | -41.99328039 |
| 51659847 | 22005451 | 189 - Other curve | 2022-09-07T00:42:00Z | 2022-09-01Z | Minor | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tasman Highway, Cranbrook, Glamorgan-Spring Bay | A0113 | 38 | A | 8.86 | | Light Vehicle | 148.0981243 | -41.99328189 |

Lisdillon Package: South of Rocky Hills crash statistics

| ID | VCRN | DCA DESCRIPTION | CRASH DATE TIME | REPORT DATE | SEVERITY | VISITED | SURFACE TYPE | SURFACE CONDITIONS | LIGHT CONDITION | CENTRE LINE | SPEED ZONE | LOCATION DESCRIPTION | DIER ROAD NO | DIER ROAD LINK NO | DIER CWY CODE | DIER CHNG | CRASH TIME MS | UNIT TYPES | LAT | LONG |
|--------|------|-----------------------------------------------------|-------------------------|-------------|----------------------|---------|--------------|--------------------|---------------------------------|-------------------------------------|------------|------------------------------------------------------|--------------|-------------------|---------------|-----------|---------------|------------------------------|-------------|-------------|
| 354707 | 181 | Off-carriageway right bend | 2011-04-30T09:29:00Z | 2011-04-29Z | First Aid | Yes | Sealed | Dry | Daylight | Double - one broken, one continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 8.06 | 1:30:12Z | Motorcycle | 147.999911 | -42.2802628 |
| 354707 | 181 | Off-right bend into object/parked vehicle | 2010-11-28T23:28:00Z | 2010-11-24Z | Minor | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 8.06 | 1:29:51Z | Light Vehicle | 147.999920 | -42.2803623 |
| 354707 | 181 | Off-right bend into object/parked vehicle | 2006-11-05T03:45:00Z | 2006-11-04Z | Serious | Yes | Sealed | Dry | Daylight | None | 50 | Cottons Drive, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 1.66:15Z | Motorcycle | 147.99046 | -42.3065051 | |
| 354707 | 181 | Accident or broken down | 2006-11-24T06:50:00Z | 2006-11-24Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Double - one broken, one continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 8.61 | 1:16:12Z | Heavy Vehicle, Light Vehicle | 147.983263 | -42.2981429 |
| 354707 | 181 | Off-carriageway into object or parked vehicle | 2007-02-05T07:01:00Z | 2007-02-01Z | Property Damage Only | No | Sealed | Dry | Daylight | Not stated | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 8.21 | 1:18:51Z | Light Vehicle | 147.999920 | -42.2803623 |
| 254707 | 130 | Vehicles in same lane/ near end | 2002-03-13T06:50:00Z | 2002-03-04Z | Minor | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 7.54 | 1:02:12Z | Heavy Vehicle, Light Vehicle | 147.997518 | -42.284927 |
| 254707 | 130 | Off-left bend into object/parked vehicle | 2003-11-18T02:45:00Z | 2004-01-05Z | Minor | Yes | Sealed | Dry | Daylight | Single continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 9.39 | 1:07:12Z | Light Vehicle | 148.03099 | -42.2609533 |
| 254707 | 136 | Vehicles in parallel lane/ right turn side swipe | 2002-06-05T07:01:00Z | 2004-01-15Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 8.51 | 1:05:12Z | Light Vehicle | 147.999920 | -42.2803623 |
| 254707 | 181 | Off-left bend into object/parked vehicle | 2002-10-28T23:25:00Z | 2002-12-23Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 7.28 | 1:04:12Z | Light Vehicle | 147.996254 | -42.2872736 |
| 254707 | 181 | Off-left bend into object/parked vehicle | 2002-09-17T23:25:00Z | 2003-11-05Z | First Aid | Yes | Sealed | Wet | Not stated | None | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 27 | A | 9.77 | 1:03:12Z | Light Vehicle | 148.032489 | -42.3384947 |
| 254707 | 120 | Wrong side/other head on (not overtaking) | 2002-09-22T03:00:00Z | 2002-11-05Z | First Aid | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 8.65 | 1:02:12Z | Light Vehicle | 147.999920 | -42.2803623 |
| 254707 | 181 | Off-left bend into object/parked vehicle | 2001-08-18T06:34:00Z | 2001-09-06Z | Serious | Yes | Sealed | Dry | Daylight | Single broken | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 2.24 | 3:08:11Z | Light Vehicle | 147.957056 | -42.3184679 |
| 254707 | 152 | Pulling out | 2002-02-04T10:00:00Z | 2002-06-16Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Double - one broken, one continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 10.16 | 1:01:12Z | Light Vehicle | 148.002121 | -42.2672992 |
| 254707 | 173 | Right off carriageway into object or parked vehicle | 2001-11-23T08:00:00Z | 2001-01-21Z | Minor | Yes | Sealed | Dry | Daylight | Single broken | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 31 | A | 0.98 | 1:04:12Z | Light Vehicle | 148.00921 | -42.2537571 |
| 254707 | 181 | Off-right bend into object/parked vehicle | 2001-03-03T18:30:00Z | 2001-04-19Z | Serious | Yes | Sealed | Dry | Daylight | Double - one broken, one continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 8.44 | 9:05:11Z | Light Vehicle | 148.002955 | -42.2781088 |
| 254707 | 181 | Off-left bend into object/parked vehicle | 2001-09-18T14:00:00Z | 2004-08-08Z | Fatal | Yes | Sealed | Not known | Darkness (without street light) | Double - one broken, one continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 31 | A | 0.54 | 1:06:12Z | Light Vehicle | 148.002423 | -42.2609198 |
| 254707 | 136 | Vehicles in parallel lane/ right turn side swipe | 2002-12-29T02:00:00Z | 2003-01-30Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 8.61 | 1:05:12Z | Motorcycle | 148.000206 | -42.2707515 |
| 254707 | 130 | Vehicles in same lane/ near end | 2001-11-17T02:45:00Z | 2002-12-17Z | Property Damage Only | No | Sealed | Wet | Daylight | Not stated | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 1.57 | 1:03:12Z | Light Vehicle | 147.951542 | -42.3242606 |
| 254707 | 184 | Out of control on carriageway | 2004-01-30T07:45:00Z | 2004-08-08Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Double broken | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 0.65 | 1:00:12Z | Light Vehicle | 147.945215 | -42.3201242 |
| 254707 | 184 | Out of control on carriageway | 2004-02-02T23:30:00Z | 2004-08-16Z | First Aid | No | Sealed | Dry | Daylight | Double continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 8.61 | 1:05:12Z | Light Vehicle | 148.000206 | -42.2707515 |
| 254707 | 181 | Off-left bend into object/parked vehicle | 2003-03-03T11:00:00Z | 2003-06-17Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 7.33 | 1:05:12Z | Light Vehicle | 148.002221 | -42.2788901 |
| 254707 | 179 | Other straight | 2004-10-01T02:00:00Z | 2004-11-09Z | Property Damage Only | No | Sealed | Not known | Not stated | Not stated | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 27 | A | 8.59 | 1:05:12Z | Light Vehicle | 147.935287 | -42.3526796 |
| 254707 | 189 | Other curve | 2004-12-13T06:00:00Z | 2005-01-10Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Double - one broken, one continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 27 | A | 9.84 | 1:10:12Z | Light Vehicle | 147.930337 | -42.3343893 |
| 254707 | 181 | Off-right bend into object/parked vehicle | 2005-05-05T07:08:45:00Z | 2005-06-09Z | Property Damage Only | Yes | Sealed | Dry | Darkness (without street light) | Double continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 4.47 | 1:12:12Z | Light Vehicle | 148.000159 | -42.2778852 |
| 354707 | 181 | Off-right bend into object/parked vehicle | 2005-01-11T18:00:00Z | 2006-01-12Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Double - one broken, one continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 8.65 | 1:14:12Z | Light Vehicle | 147.990687 | -42.2918446 |
| 354707 | 181 | Off-right bend into object/parked vehicle | 2005-11-18T02:45:00Z | 2006-11-20Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Double broken | 100 | Tamman Highway, Portonbury, Glamorgan Spring Bay | A0113 | 29 | A | 1.74 | 1:13:12Z | Light Vehicle | 147.951451 | -42.3210638 |
| 354707 | 120 | Wrong side/other head on (not overtaking) | 2009-03-01T06:30:00Z | 2009-03-11Z | Property Damage Only | No | Sealed | Dry | Daylight | Double continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 8.69 | 1:23:12Z | Light Vehicle | 148.004294 | -42.2760864 |
| 354707 | 181 | Off-left bend into object/parked vehicle | 2005-06-05T09:20:00Z | 2006-06-04Z | Minor | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 0.66 | 1:24:12Z | Light Vehicle | 147.945245 | -42.3201242 |
| 354707 | 181 | Off-right bend into object/parked vehicle | 2005-06-13T07:33:00Z | 2006-06-13Z | First Aid | Yes | Sealed | Dry | Daylight | Double - one broken, one continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 8.07 | 1:23:12Z | Light Vehicle | 147.945245 | -42.3201242 |
| 354707 | 181 | Off-left bend into object/parked vehicle | 2009-02-24T03:50:00Z | 2009-02-24Z | Minor | Yes | Sealed | Wet | Daylight | Double continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 0.72 | 1:24:12Z | Light Vehicle | 147.945852 | -42.3287687 |
| 354707 | 174 | Out of control on carriageway | 2004-04-02T09:00:00Z | 2009-04-14Z | Minor | No | Unsealed | Dry | Daylight | Not known | Not stated | Brennans Road, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 0.72 | 1:24:12Z | Motorcycle | 147.93204 | -42.3103508 |
| 354707 | 180 | Off-carriageway right bend | 2005-05-24T03:30:00Z | 2005-05-25Z | First Aid | Yes | Sealed | Dry | Daylight | Double - one broken, one continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 8.07 | 1:24:12Z | Light Vehicle | 147.945245 | -42.3201242 |
| 354707 | 181 | Off-right bend into object/parked vehicle | 2010-02-01T06:30:00Z | 2010-02-01Z | Property Damage Only | No | Sealed | Dry | Daylight | Not known | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 7.78 | 1:28:12Z | Light Vehicle | 147.998258 | -42.2811798 |
| 354707 | 173 | Right off carriageway into object or parked vehicle | 2010-07-02T07:11:00Z | 2010-07-03Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 31 | A | 1.66 | 1:28:12Z | Light Vehicle | 148.006376 | -42.2527875 |
| 354707 | 180 | Off-carriageway right bend | 2005-05-28T07:25:00Z | 2010-06-26Z | First Aid | Yes | Sealed | Dry | Daylight | Double - one broken, one continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 8.01 | 1:28:12Z | Light Vehicle | 148.006376 | -42.2527875 |
| 354707 | 180 | Off-carriageway right bend | 2012-03-01T02:54:00Z | 2012-03-29Z | Minor | Yes | Sealed | Wet | Daylight | Double continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 0.81 | 1:33:12Z | Light Vehicle | 147.944511 | -42.3209111 |
| 354707 | 181 | Off-right bend into object/parked vehicle | 2012-03-26T04:57:00Z | 2012-03-15Z | Serious | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 0.81 | 1:33:12Z | Light Vehicle | 147.933105 | -42.3213418 |
| 354707 | 181 | Off-right bend into object/parked vehicle | 2009-03-05T09:30:00Z | 2009-03-05Z | First Aid | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 4.46 | 1:33:12Z | Light Vehicle | 147.940271 | -42.3213418 |
| 354707 | 181 | Off-right bend into object/parked vehicle | 2011-12-15T23:28:00Z | 2012-11-16Z | Serious | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 5.15 | 1:33:12Z | Light Vehicle, Pedestrian | 147.979189 | -42.3000828 |
| 354707 | 181 | Off-right bend into object/parked vehicle | 2011-04-01T23:22:00Z | 2012-02-04Z | Minor | No | Unsealed | Wet | Darkness (without street light) | Double continuous | 100 | Swanton Road, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 1.94 | 1:33:12Z | Light Vehicle | 147.945245 | -42.3201242 |
| 354707 | 166 | Subst object on carriageway | 2006-06-05T09:04:00Z | 2006-06-04Z | Minor | No | Unsealed | Dry | Daylight | None | <40 | Off road at Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 1.15:15Z | Motorcycle | 148.011457 | -42.2584991 | |
| 78880 | 136T | Animal (not ridden) | 2013-06-28T02:43:00Z | 2013-06-27Z | Property Damage Only | Yes | Sealed | Dry | Darkness (without street light) | Single broken | 100 | Tamman Highway, Portonbury, Glamorgan Spring Bay | A0113 | 29 | A | 1.68 | 1:37:12Z | Light Vehicle | 147.952818 | -42.3223029 |
| 354707 | 181 | Off-right bend into object/parked vehicle | 2013-03-24T07:26:00Z | 2013-03-24Z | Minor | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 8.51 | 1:36:12Z | Light Vehicle | 147.999920 | -42.2773851 |
| 354707 | 181 | Off-right bend into object/parked vehicle | 2009-03-19T06:45:00Z | 2009-03-22Z | First Aid | Yes | Sealed | Dry | Daylight | Double broken | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 4.44 | 1:22:12Z | Light Vehicle | 147.93088 | -42.305456 |
| 354707 | 167 | Animal (not ridden) | 2007-02-17T08:37:00Z | 2007-02-16Z | Property Damage Only | Yes | Sealed | Dry | Darkness (without street light) | Single broken | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 0.65 | 1:22:12Z | Light Vehicle | 147.992965 | -42.2899331 |
| 354707 | 181 | Off-right bend into object/parked vehicle | 2008-11-04T03:30:00Z | 2008-11-06Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 8.07 | 1:23:12Z | Light Vehicle | 147.999920 | -42.2803623 |
| 534516 | 156T | Off-carriageway left bend | 2011-02-28T22:22:00Z | 2011-02-26Z | Minor | Yes | Sealed | Wet | Daylight | Single broken | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 6.75 | 1:45:12Z | Light Vehicle | 147.945855 | -42.3287667 |
| 550094 | 156T | Right off carriageway into object or parked vehicle | 2011-04-11T23:33:00Z | 2011-04-13Z | Minor | Yes | Sealed | Dry | Daylight | Double - one broken, one continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 7.95 | 1:45:12Z | Light Vehicle | 147.999920 | -42.2814548 |
| 354707 | 121 | Off-carriageway right bend | 2009-10-02T06:30:00Z | 2009-10-02Z | Minor | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 0.98 | 1:23:12Z | Light Vehicle | 147.999920 | -42.3103508 |
| 466214 | 156T | Off-left bend into object/parked vehicle | 2014-12-14T03:40:00Z | 2014-12-13Z | Minor | Yes | Sealed | Dry | Daylight | Single continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 2.77 | 1:42:12Z | Light Vehicle | 147.951734 | -42.3218821 |
| 354707 | 120 | Wrong side/other head on (not overtaking) | 2007-07-01T04:45:00Z | 2007-06-30Z | Property Damage Only | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 5.56 | 1:18:12Z | Light Vehicle | 147.982841 | -42.2941113 |
| 354707 | 173 | Right off carriageway into object or parked vehicle | 2007-02-28T23:23:00Z | 2007-03-13Z | Minor | Yes | Sealed | Dry | Darkness (without street light) | Double continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 31 | A | 0.78 | 1:19:12Z | Light Vehicle | 148.006376 | -42.2527875 |
| 354707 | 181 | Off-right bend into object/parked vehicle | 2008-08-18T05:45:00Z | 2007-08-17Z | Minor | Yes | Sealed | Dry | Daylight | Double - one broken, one continuous | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 8.02 | 1:19:12Z | Light Vehicle | 147.999664 | -42.2808796 |
| 354707 | 136 | Vehicles in parallel lane/ right turn side swipe | 2008-03-23T09:13:00Z | 2008-03-22Z | Minor | Yes | Sealed | Dry | Daylight | Double broken | 100 | Tamman Highway, Little Swanton, Glamorgan Spring Bay | A0113 | 29 | A | 7.23 | 1:21:12Z | Light Vehicle | 147.99081 | -42.2874598 |
| 354707 | 181 | Off-left bend into object/parked vehicle | 2010-03-01T07:14:00Z | 2010-03-01Z | Serious | Yes | Sealed | Dry | Daylight | Double continuous | | | | | | | | | | |

| Lisdillon Package: North of Triabunna crash statistics | | | | | | | | | | | | | | | | | | | | | |
|--------------------------------------------------------|---------|----------------------------------------------------------|----------------------|-------------|----------------------|---------|--------------|--------------------|---------------------------------|-------------------|------------|-------------------------------------------------|--------------|-------------------|---------------|-----------|---------------|------------|---------------|------------|-------------|
| ID | VCRN | DCA DESCRIPTION | CRASH DATE TIME | REPORT DATE | SEVERITY | VISITED | SURFACE TYPE | SURFACE CONDITIONS | LIGHT_CONDITION | CENTRE_LINE | SPEED_ZONE | LOCATION DESCRIPTION | DIER_ROAD_NO | DIER_ROAD_LINK_NO | DIER_CWY_CODE | DIER_CHNG | CRASH TIME MS | UNIT_TYPES | LAT | LOn | |
| 2E+07 | | 120 - Wrong side/other head on (not overtaking) | 2003-12-06T02:40:00Z | 2004-01-05Z | Serious | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tasman Highway, Triabunna, Glamorgan/Spring Bay | A0113 | | 25 | A | 0.77 | 1.07E+12 | Light Vehicle | 147.927824 | -42.4928944 |
| 2E+07 | | 182 - Off carriageway left bend | 2003-06-13T09:30:00Z | 2003-09-18Z | Property Damage Only | Yes | Sealed | Not known | Not stated | Double continuous | 100 | Tasman Highway, Triabunna, Glamorgan/Spring Bay | A0113 | | 25 | A | 0.76 | 1.05E+12 | Light Vehicle | 147.927741 | -42.4929934 |
| 3E+07 | | 183 - Off left bend into object/parked vehicle | 2009-01-28T01:55:00Z | 2009-01-27Z | Minor | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tasman Highway, Triabunna, Glamorgan/Spring Bay | A0113 | | 25 | A | 1.2 | 1.23E+12 | Motorcycle | 147.932565 | -42.4913002 |
| 2019931 | 1.7E+07 | 120 - Wrong side/other head on (not overtaking) | 2017-03-14T18:15:00Z | 2017-03-14Z | Minor | Yes | Sealed | Dry | Dawn / Dusk | Double continuous | 100 | Tasman Highway, Triabunna, Glamorgan/Spring Bay | A0113 | | 25 | A | 1.23 | | Light Vehicle | 147.932743 | -42.4911631 |
| 1504123 | 1.6E+07 | 179 - Other straight | 2016-03-13T18:45:00Z | 2016-03-12Z | Property Damage Only | Yes | Sealed | Wet | Darkness (without street light) | Single broken | 100 | Tasman Highway, Triabunna, Glamorgan/Spring Bay | A0113 | | 25 | A | 0.53 | 1.46E+12 | Light Vehicle | 147.926395 | -42.4946206 |
| 1700403 | 1.6E+07 | 189 - Other curve | 2016-05-01T11:38:00Z | 2016-05-02Z | Minor | Yes | Sealed | Wet | Darkness (without street light) | Double continuous | 100 | Tasman Highway, Triabunna, Glamorgan/Spring Bay | A0113 | | 25 | A | 0.78 | 1.46E+12 | Light Vehicle | 147.927918 | -42.4927777 |
| 1989361 | 1.6E+07 | 181 - Off right bend into object/parked vehicle | 2016-12-11T04:35:00Z | 2016-12-10Z | Serious | Yes | Sealed | Dry | Daylight | Double continuous | 100 | Tasman Highway, Triabunna, Glamorgan/Spring Bay | A0113 | | 25 | A | 0.8 | | Light Vehicle | 147.928038 | -42.492662 |
| 3.2E+07 | 2.2E+07 | 171 - Left off carriageway into object or parked vehicle | 2022-08-05T11:00:00Z | 2022-08-05Z | Minor | Yes | Sealed | Wet | Darkness (without street light) | Single broken | 100 | Tasman Highway, Triabunna, Glamorgan/Spring Bay | A0113 | | 25 | A | 1.85 | | Light Vehicle | 147.934314 | -42.4836509 |